



CAL FIRE
San Luis Obispo
County Fire Department

635 N. Santa Rosa • San Luis Obispo, CA 93405
Phone: 805.543.4244 • Fax: 805.543.4248
www.calfireslo.org

Scott M. Jalbert, Unit Chief

February 4, 2021

TO: LOCSO Board of Directors

FROM: Paul Provence, North Coast Battalion Chief

SUBJECT: Agenda Item 7F – 02/04/2021 Board Meeting

Adopt Resolution Declaring Medic Engine-215 Vehicle Surplus to District Needs and Authorize the Sale of Surplus Vehicle [Recommend Adopt Resolution 2021-07]

DESCRIPTION

This staff note requests your Board declare Medic Engine 215, a 1997 Pierce Quantum, surplus to Station 15 – South Bay and sell it to deposit the proceeds into Fund 301 Line Item 9504, Vehicle Replacement Reserve.

STAFF RECOMMENDATION

This item will be approved along with the Consent Calendar unless it is pulled by a Director for separate consideration. If so, staff recommends that the Board adopt the following motion:

Motion: I move the Board declare Medic Engine 215, a 1997 Pierce Quantum, surplus to Station 15 – South Bay and authorize the sell with the proceeds deposited into Fund 301 Line Item 9504, Vehicle Replacement Reserve.

DISCUSSION

In October 2020, Engine 215 was placed out of service due to mechanical issues. These issues include engine maintenance consistent with the age of the apparatus, fire pump repairs, and several air compressor and service airline failures.

In November 2020, the status of the Engine 215 was determined after diagnostics at a local fire apparatus service vendor. The estimated cost to repair Engine 215 was starting at a minimum of \$9,000. Given the age of the apparatus, estimated cost of repairs, and the overall value, it was decided not to repair Engine 215.

In March 2020, the LOSCD Board adopted Resolution 12C(a) authorizing the purchase of a replacement Medic Engine 15. The purchase is consistent with vehicle replacement goals established through past recommendations from ESAC committee and revenues from LOCS D Vehicle Sinking Fund. Replacement of Engine 215 has also been forecasted for the last several years. CAL FIRE/SLO County Fire Department generally recommends that fire engines are replaced between 15 and 20 years of service. Engine 215 has exceeded recommended service lengths in both FRONT LINE and RESERVE status.

The current Medic Engine 15, a 2013 Spartan Metro Star, will be placed in RESERVE (Engine 215) status upon arrival of the new Medic Engine 15. Estimated delivery of the new Medic Engine 15 is Fall 2021. Due to the age of the apparatus and estimated repairs, current market value is approximately \$3,000 to \$7,000. It is our recommendation that staff sell the engine to a third party, if possible, rather than list it for auction as the time and effort of administrative and uniform staff would be inefficient.

FINANCIAL IMPACT

Staff has been anticipating the sale of Medic Engine-215 since your Board's approval of the purchase of a new Medic Engine. CAL FIRE/Station 15 – South Bay Fire Staff expects to deposit any proceeds from the sale of Medic Engine-215 into the Fund 301 Vehicle Reserve, Line Item 9504.

Best Regards,

Paul Provence

Paul Provence
North Coast Battalion Chief
CAL FIRE / San Luis Obispo County Fire Department

Attachments
2021-07 Resolution
Estimate for Repairs

RESOLUTION NO. 2021-07

**A RESOLUTION OF THE BOARD OF DIRECTORS
OF THE LOS OSOS COMMUNITY SERVICES DISTRICT
DECLARING MEDIC RESCUE-215 VEHICLE SURPLUS TO DISTRICT NEEDS
AND AUTHORIZING THE SALE OF SURPLUS VEHICLE**

WHEREAS, a certain vehicle described as a 1997 Pierce Quantum is surplus to District Needs; and

WHEREAS, the Board desires to dispose of this surplus vehicle in as efficient and cost effective manner as possible,

NOW, THEREFORE, THE BOARD OF DIRECTORS OF THE LOS OSOS COMMUNITY SERVICES DISTRICT DOES HERBY RESOLVE, DECLARE AND DETERMINE THAT:

1. The vehicle described as a 1997 Pierce Quantum is surplus to District needs.
2. The Board of Directors authorizes staff to sell this surplus vehicle.
3. Monies collected from the sale of this surplus vehicle are to be added to the Fire Vehicle Replacement Reserve Fund.

On the motion of Director _____, seconded by Director _____, and on the following roll call vote, to wit:

Ayes: _____
Nays: _____
Abstain: _____
Absent: _____

The foregoing resolution is hereby passed, approved, and adopted by the Board of Directors of the Los Osos Community Services District this 4th day of February 2021.

Christine M. Womack
President, Board of Directors

ATTEST:

APPROVED AS TO FORM:

Ron Munds
General Manager and Secretary to the Board

Jeffrey Minnery
District Legal Counsel



SOUTH COAST
EMERGENCY VEHICLE SERVICE

PARTS SERVICE & CENTER

FROM: Terry Skrobrak
TEL 805-354-4399
FAX #909-930-5258

ESTIMATE

TS07222020A

CUSTOMER:
Cal Fire

ADDRESS:
635 N SANTA ROSA
SAN LUIS OBISPO CA 93405

CONTACT:
KEVIN

PHONE:
805-903-3430

ITEM	DESCRIPTION	HRS	LABOR	PARTS	FEES	TOTAL
5	Repair water in leak in pump house area.	3	\$130.00			\$390.00
	1.5"x2 STD BLK NIPPLE (BIS-1.5X2NPL)			\$3.73		\$3.73
	1-1/2" 304SS 150# THRD ELBOW90 (BIN-112-304SS)			\$24.17		\$24.17
	1.5" AKRON REBUILD KIT W/METAL BALL (AKB-8804)			\$116.00		\$116.00
6	Find & repair air leaks on chassis and Cab step system. Replace defective cab step compressor. Replace leaking components of step system.	6	\$130.00			\$780.00
	STEP AIR COMPRESSOR(PIE-2494651)			\$530.81		\$530.81
	AIR STEP CYLINDER(PIE-2129283)for driver,captain,captain rear			\$206.29		\$618.87
	QUANTUM VALVE STEP ASSY. (PIE-46-4835)for capt. rear/ driver			\$381.69		\$763.38
	DOT FITTINGS, HOSE, LOOM, THREAD TAPE AND ZIP TIES			\$100.00		\$100.00
7	Replace broken rear deck light and repair defective wiring	2	\$130.00			\$260.00
	LIGHT,SPT/FLD, COLLING FX12 W/SQ B (PIE-61-0412)			\$487.94		\$487.94
	MISC WIRING, BUTT CONN., LOOM AND ZIP TIES			\$25.00		\$25.00
8	Replace and/or repair the multiple lights inside and outside of truck that are out.	2	\$130.00			\$260.00
	LIGHTING/ LIGHT BULBS MISC(MULTIPLE)			\$50.00		\$50.00
	THIS ESTIMATE DOES NOT INCLUDE SHIPPING CHARGES					
	PAGE 1 TOTAL					
	SUBTOTAL LABOR, MATERIALS, FEES					\$4,019.90
	SALES TAX 7.75%					\$8,036.07
	TOTAL ESTIMATE					\$8,493.50

NOTE: This is an estimate and not a formal quotation due to the possibility of unknown hidden damage. Should actual work costs exceed this estimate, the purchaser shall be contacted for approval prior to work continuing. Actual (true) not estimated, costs shall be reflected in the invoice. All estimates are valid for 30 days. Estimate does not include any shipping charges which will be added to invoice. PO required on all orders. Net -30 terms. Pick-up/delivery not included unless otherwise noted. A 90 day limited workmanship guaranty will be provided on all work performed.



SOUTH COAST
EMERGENCY VEHICLE SERVICE

PARTS SERVICE & CENTER

FROM: Terry Skrobrak
TEL 805-354-4399
FAX #909-930-5258

ESTIMATE

TS11252019A

CUSTOMER: Cal Fire
ADDRESS: 635 N SANTA ROSA
SAN LUIS OBISPO CA 93405
CONTACT: Kevin
PHONE: 805-903-3430

ITEM	DESCRIPTION	HRS	LABOR	PARTS	FEES	TOTAL
	The following estimate is for Pierce job# EA430 unit# 215 from list provided by the customer and the list gathered from our inspection. If additional repairs are needed other than what listed a revised estimate will be made.					
1	Replace both mirrors. Flattened door skin where mirror attaches MIRROR,ELECT,RH (PIE-46-5434) MIRROR,ELECT,LH (PIE-46-5433)	2	\$130.00	\$465.78 \$465.78		\$260.00 \$465.78 \$465.78
2	Replace cracked and unreadable pump panel gauges GAUGE,2.5",C1(PIERCE LOGO) PIE-2450708-0001 (X7)	2.5	\$130.00	\$134.42		\$325.00 \$940.94
3	Replace dash warning lamp indicator along with burnt gauge light bulbs CKT BOARD ASY,DISPLAY (PIE-60-0888-0001) MINIATURE LAMP (CRQ-11009) X7	1	\$130.00	\$690.00 \$3.78		\$130.00 \$690.00 \$26.46
4	Repair captains, captains rear and drivers rear cracked welds. replace latch & strikers for captains door. Repair lower door skin inserts & replace all cracked plastic door panels. PASS. SIDE DOOR PANEL (PIE-46-2378) X2 DRIVER SIDE DOOR PANEL (PIE-46-2377) X2 LATCH,DBK ROTOR,RH (PIE-1993168) DOOR STRIKER (PIE-80-0310) SNAP NUT,#10,#8 (MCM-9850A485) X12	8	\$130.00			\$1,040.00
			\$145.11 \$123.34 \$30.53 20.51 0.46			\$290.22 \$246.68 30.53 \$20.51 \$5.52
	CONTINUE ON PAGE 2					\$4,937.42

NOTE: This is an estimate and not a formal quotation due to the possibility of unknown hidden damage. Should actual work costs exceed this estimate, the purchaser shall be contacted for approval prior to work continuing. Actual (true), not estimated, costs shall be reflected in the invoice. All estimates are valid for 30 days. Estimate does not include any shipping charges which will be added to invoice. PO required on all orders. Net -30 terms. Pick-up/delivery not included unless otherwise noted. A 90 day limited workmanship guaranty will be provided on all work performed.